



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D5718-3
Job Sheet 204337



Part No: D5718-3

Job Qty: 8 pcs **16**

Part Name: Bearpaw Clamp



Part Weight: 0 lbs

Job Created: 12/6/19

Due Date: 1/17/20 **Dec 20**

Type: Stock **Sold**

Status: New

Job Tracking No:

Created By: Jennifer Renwick

Description:

Priority: Medium

Note: DWG D5718 REV.A IPP REV:A 19.06.05 NEW ISSUE DD VERF:JFS

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Waterjet - Flow - 1	8 pcs		1/17/20	0.17	0.40	Waterjet - Flow		Dec 19/12/18
110	QC 2	8 pcs		1/17/20	0.00	0.00	QC 2 - 1		
							QC 2 - 12		
							QC 2 - 14		
							QC 2 - 17		
							QC 2 - 19		
							QC 2 - 2		
							QC 2 - 20		
							QC 2 - 22		
							QC 2 - 23		
							QC 2 - 25		
							QC 2 - 32		
							QC 2 - 33		
							QC 2 - 35		
							QC 2 - 39		
							QC 2 - 4		
							QC 2 - 40		
							QC 2 - 44		
							QC 2 - 45		
							QC 2 - 48		Dec 19/12/18
							QC 2 - 49		
							QC 2 - 50		
							QC 2 - 51		
							QC 2 - 52		
							QC 2 - 57		
							QC 2 - 62		
							QC 2 - 63		
							QC 2 - 8		
							QC 2 - 66		
							QC 2 - 64		

Plex 12/6/19 11:52 AM Dart.Renwick.Jennife

12/6/2019




[Dart Hawkesbury] Job Sheet - Renwick, Jennifer

120 QC 8	8 pcs	1/17/20	0.00 0.00	QC 2 - 65	
				QC 2 - 5	
				QC 2 - 71	
				QC 2 - 73	
				QC 2 - 69	
				QC 8 - 12	
				QC 8 - 14	
				QC 8 - 17	
				QC 8 - 20	
				QC 8 - 25	
				QC 8 - 3	
				QC 8 - 32	
				QC 8 - 33	
				QC 8 - 35	
				QC 8 - 39	
				QC 8 - 4	
				QC 8 - 44	
				QC 8 - 45	
				QC 8 - 49	
				QC 8 - 58	
				QC 8 - 8	
				QC 8 - 9	
				QC 8 - 68	
				QC 8 - 67	
				QC 8 - 1 (A)	
				QC 8 - 47	
				QC 8 - 40	
				QC 8 - 52	
				QC 8 - 23	
				QC 8 - 57	
				QC 8 - 76	
				QC 8 - 61	
130 Small Fab - Brake NC - B4B	8 pcs	1/17/20	0.25 0.32	Small Fab - Brake - 1 - B4B	DAS 30 DEC 20 2019 9-89
				Small Fab - Brake - 2 - B4B	
				Small Fab - Brake - 3 - B4B	
140 QC 5	8 pcs	1/17/20	0.00 0.00	QC 5 - 10	
				QC 5 - 12	
				QC 5 - 17	
				QC 5 - 18	
				QC 5 - 19	
				QC 5 - 22	
				QC 5 - 24	
				QC 5 - 3	
				QC 5 - 43	
				QC 5 - 49	
				QC 5 - 51	
				QC 5 - 58	
				QC 5 - 68	
				QC 5 - 9	
				QC 5 - 50	
				QC 5 - 30	
				QC 5 - 40	
				QC 5 - 61	
				QC 5 - 81	
150 Packaging 3-1 - Stock - B4B	8 pcs	1/17/20	0.00 0.00	Packaging 3 - 1 - B4B	DAS 40 DEC 20 2019 9-89
				Packaging 3 - 2 - B4B	
				Packaging 3 - 3 - B4B	

Plex 12/6/19 11:52 AM Dart.Renwick.Jennifer

				Packaging 3 - 4 - B4B	
				Packaging 3 - 5 - B4B	
				Packaging 3 - 6 - B4B	DAS
				Packaging 3 - 7 - B4B	20
				Packaging 3 - 8 - B4B	9-89
				Packaging 3 - 9 - B4B	
				Packaging 3 - 10 - B4B	
				Packaging 3 - 11 - B4B	
				Packaging 3 - 12 - B4B	
				Packaging 3 - 13 - B4B	
				Packaging 3 - 14 - B4B	
				Packaging 3 - 15 - B4B	
				Packaging 3 - 16 - B4B	
				Packaging 3 - 17 - B4B	
				Packaging 3 - 18 - B4B	
				Packaging 3 - 19 - B4B	
				Packaging 3 - 20 - B4B	
				Packaging 3 - 21 - B4B	
				Packaging 3 - 22 - B4B	
				Packaging 3 - 23 - B4B	
				Packaging 3 - 24 - B4B	
				Packaging 3 - 25 - B4B	
				Packaging 3 - 26 - B4B	
				Packaging 3 - 27 - B4B	
				Packaging 3 - 28 - B4B	
				Packaging 3 - 29 - B4B	
				Packaging 3 - 30 - B4B	
				Packaging 3 - 31 - B4B	
				Packaging 3 - 32 - B4B	
				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	
				Packaging 3 - 36 - B4B	
160	QC 21 - SA	8	1/17/20	0.00 0.00	QC 21 - SA - 21
		pcs			QC 21 - SA - 70
					QC 21 - SA - 53
Part Op 100 - 1-Cut as per Dwg Dwg Rev: <u>A</u> Prog Rev: <u>A</u> 2-Deburr if necessary Descriptions: 110 - QC2- Inspect parts off machine FAI/FAIB 120 - QC8- Inspect parts - second check 130 - Form as per dwg 140 - QC5- Inspect part completeness to step on W/O 150 - Identify as per dwg & Stock Location: _____ 160 - QC21- Final Inspection - Work Order Release					DEC 20 2019 DEC 7 11:10
Job BOM					
Part / Item	Component Name	Quantity	Operation	Container	
M304S13GA	304/316 .090" Sheet	.7640 sf (.0955 ea)	100-Waterjet - Flow - 1	F103033	
Job Allocations					
Operation	Component Part	Required	Inventory	Allocated	
100-Waterjet - Flow - 1	M304S13GA	1	7	0	
Part Specifications					
Specifications could not be found.					

Plex 12/6/19 11:52 AM Dart.Renwick.Jennifer



D5718-3 BEARPAW CLAMP

- NOTES:**
- 1) MATERIAL: MAKE FROM D5718-3F
 - 2) FINISH: NONE
 - 3) TOLERANCES: PER DART OSI 018 UNLESS OTHERWISE NOTED
 - 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 - 5) BREAK SHARP EDGES: N/A
 - 6) IDENTIFICATION: IDENTIFY PER OSI 044 6:1
 - 7) WEIGHT: 0.27 lbs

RELEASED
2019 OCT 09

APPROVED

DESIGN	RF	RF	DART AEROSPACE USA, INC.
DRAWN	RF	FM	HILSBORO, OR
CHECKED	FM	DD	D5718
MFG. APPR.	VS	VS	BEARPAW CLAMP
APPROVED	VS	VS	SCALE
DATE	19.07.19	DATE	NTS

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 204337

GOVERNMENT PROPERTY: THIS DRAWING IS THE PROPERTY OF DART AEROSPACE USA, INC. AND IS LOANED TO YOU BY THE U.S. GOVERNMENT. IT IS TO BE USED FOR THE PURPOSES SPECIFIED IN THE ORDER AND IS NOT TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM, WITHOUT PERMISSION IN WRITING FROM DART AEROSPACE USA, INC.

Entered: _____ Date: _____

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only



Job: _____ Part No. _____		DISPOSITION Rework ☐ ☐ ☐ Scrap ☐ ☐ ☐ Use-as-is ☐ ☐ ☐		DEPARTMENT/PROCESS Skid-tube ☐ ☐ ☐ ☐ ☐ Machining ☐ ☐ ☐ ☐ ☐ Large Fab ☐ ☐ ☐ ☐ ☐		Cross tube ☐ ☐ ☐ ☐ ☐ Small Fab ☐ ☐ ☐ ☐ ☐ Finishing ☐ ☐ ☐ ☐ ☐		Eng. (Non-AW) ☐ ☐ ☐ ☐ ☐ Prod. Eng. Coord. ☐ ☐ ☐ ☐ ☐ Rec/Store/Packaging ☐ ☐ ☐ ☐ ☐		Engineering ☐ ☐ ☐ ☐ ☐ Water Jet ☐ ☐ ☐ ☐ ☐ Supplier ☐ ☐ ☐ ☐ ☐ Quality ☐ ☐ ☐ ☐ ☐			
Date : _____		Sequence #: _____		QTY Affected : _____		MRB (QS1042)							
Description Work Order Deviation				Disposition									
Root Cause Operator ☐ ☐ ☐ ☐ ☐ Manufacturing Process ☐ ☐ ☐ ☐ ☐ Equip/Tooling ☐ ☐ ☐ ☐ ☐ Handling/Preservation ☐ ☐ ☐ ☐ ☐ Material ☐ ☐ ☐ ☐ ☐ Product Improvement ☐ ☐ ☐ ☐ ☐ Process Improvement ☐ ☐ ☐ ☐ ☐ Human Factors ☐ ☐ ☐ ☐ ☐				FAULT CATEGORY Contamination ☐ ☐ ☐ ☐ ☐ Misaligned/off center ☐ ☐ ☐ ☐ ☐ BOM/Route ☐ ☐ ☐ ☐ ☐ Broken/Damage/Defect ☐ ☐ ☐ ☐ ☐ Incomplete/Unclear Instructions ☐ ☐ ☐ ☐ ☐ Drill Holes ☐ ☐ ☐ ☐ ☐ Fit/Function ☐ ☐ ☐ ☐ ☐								Positioned Wrong ☐ ☐ ☐ ☐ ☐ Outside Tolerance ☐ ☐ ☐ ☐ ☐ Drawing ☐ ☐ ☐ ☐ ☐ Finish ☐ ☐ ☐ ☐ ☐ Part Lost/Missing ☐ ☐ ☐ ☐ ☐ Misread ☐ ☐ ☐ ☐ ☐	
				Pressure/Forced ☐ ☐ ☐ ☐ ☐ Bending ☐ ☐ ☐ ☐ ☐ Crushing ☐ ☐ ☐ ☐ ☐ Cracks ☐ ☐ ☐ ☐ ☐ Crimp/Kink/Ripple/Wave/Twist ☐ ☐ ☐ ☐ ☐ Marks/Chatter ☐ ☐ ☐ ☐ ☐ Mislabeled ☐ ☐ ☐ ☐ ☐								Power Loss/Surge ☐ ☐ ☐ ☐ ☐ Folio/Program ☐ ☐ ☐ ☐ ☐ Grain Direction ☐ ☐ ☐ ☐ ☐ Weld ☐ ☐ ☐ ☐ ☐ Wrong Stock Pulled ☐ ☐ ☐ ☐ ☐ Out of Sequence ☐ ☐ ☐ ☐ ☐ Off-set/Set-up ☐ ☐ ☐ ☐ ☐	
				Other/Details: _____									
Completed By				Lead hand / Supervisor				QC / QA Coordinator					